For Sale; Gerbers done, analog section not seen here
Basic model: -80 -> +80 Deg C, +/- 0.2 Deg C across whole range
Features: No cal. required, RTD, filters, u-power, C/F sw, data out
Includes free calibration data out analysis spread sheet
Options: -150 -> + 500 Deg C Range & extended range
Industrial model: 4-20ma, alarm out, Relays